



Pete K. Rahn, Director

**ADDENDUM 001
REQUEST FOR QUOTATION
D610-062-RW DEMOLITION STORAGE BUILDINGS**

Bidders shall acknowledge receipt of Addendum 001 (ONE) by signing and including it with original bid. The due date for receipt of this proposal **does NOT change** by this Addendum. Accordingly, the following clarifications, questions and answers are believed to be of general interest to all potential bidders. All other terms and conditions remain unchanged and in full force.

Name and Title of Signer (Print or type)	Name and Title of Department Authority Terri Mount Sr. General Services Specialist
Bidder Signature	Department of Transportation <i>Terri Mount</i>
<div>Signature of person authorized to sign</div>	<div>Authorizing Signature</div>
Date Signed:	Date Signed: 10/5/09

**START DATE: CHANGES TO TEN (10) DAYS FROM DATE OF AWARD, COMPLETION
DATE: SEVEN (7) WORKING DAYS FROM START DATE**

REPLACE PAGE ONE OF QUOTATION WITH REVISED PAGE 1 AS SHOWN BELOW

SIGNED ADDENDUM MUST BE RETURNED WITH QUOTATION

MISSOURI DEPARTMENT OF TRANSPORTATION
INFORMAL QUOTE GUIDELINES AND DOCUMENTATION FOR PURCHASES FROM \$3,000 TO
\$24,999.99

THIS IS NOT AN ORDER



REQUEST FOR QUOTATION

It is the vendor's responsibility to read and comply with all conditions, specifications, and instructions outlined in this document.

This document and any subsequent attachments, shall supersede all confirmation forms, receipts, or any other paperwork needed to secure materials, equipment, or services.

TODAY'S DATE: OCTOBER 5, 2009	QUOTE DUE BY (DATE AND TIME): OCTOBER 22, 2009 10:00 A.M.	F.O.B. REQUIREMENTS: DESTINATION
START DATE: 10 DAYS FROM DATE OF AWARD COMPLETION DATE: 7 WORKING DAYS FROM START DATE	QUOTATION #: D610-062-RW THIS QUOTATION # SHOULD BE REFERENCED ON ALL MAILING LABELS, ENVELOPES, AND OTHER CORRESPONDENCE.	BUYER NAME/TELEPHONE NUMBER: TERRI MOUNT 314-301-1431 TERESA.MOUNT@MODOT.MO.GOV
Procurement Mailing Address #: MISSOURI DEPT. OF TRANSPORTATION DISTRICT 6 PROCUREMENT OFFICE 2309 BARRETT STATION RD. BALLWIN, MO. 63021		Job Locations: MoDOT Lemay Maintenance. Facility I-55 Outer Road 4185 Hoffmeister Ave. St. Louis, MO. 63126
Facsimile #:314-301-1437- Responses may be faxed.		

Demolition and removal of salt storage buildings below:

- All work shall be in accordance with Exhibit A- Plans, Exhibit B- MoDOT Standard Specifications, and Exhibit C- Additional Demolition and Removal Provisions. Exhibit D-Asbestos Survey.
- Visitation of work site is available on **Wednesday, October 14, 2009 from 8 AM to 11AM**, and on **Monday, October 19th from 12 PM to 3 PM, ONLY.** Questions arising from site visit shall be addressed in writing to buyer of record, responses will be published on the MoDOT General Services District 6 webpage.
- It is the responsibility of the Bidder to access MoDOT's website in order to obtain any and all addenda(s) issued during the course of this quotation process.
http://www.modot.mo.gov/business/contractor_resources/Commodities.htm
- Liquidated Damages may apply if work not completed within the time frame as noted above.

It is specifically understood that no portion of the material or any interest in the contract, shall be subcontracted, transferred, assigned or otherwise disposed of, except with the written consent of MoDOT. Request for permission to subcontract or otherwise dispose of any part of the work shall be in writing to MoDOT and accompanied by documentation showing that the organization which will perform the work is particularly experienced and equipped for such work

QTY	U/M	DESCRIPTION	COST
1	Lump sum	Demolition and removal of wooden salt storage building. Includes removal of timber and steel posts minimum 12" below grade. Existing floor of building to remain. NOTE: Existing conduit and piping attached to back of building will be removed by MoDOT forces prior to demolition of structure.	
1	Lump Sum	Demolition and removal of roof and upper wooden structure of wood/concrete salt storage building. Includes removal of angle-iron post brackets on top of concrete walls. Leave in place and do not damage lower concrete walls of structure.	